ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

 Client ID:
 M04575

 Date Received:
 09/03/09

 Date Extracted:
 09/08/09

 Date Analyzed:
 09/09/09

 Matrix:
 Water

 Units:
 ug/L (ppb)

Client: Project: Lab ID: Alaskan Copper Works PO M04575, F&BI 909039

Lab ID: 909039-01 x10 Data File: 909039-01 x10.018

Instrument: ICPMS1 Operator: btb

Low

Internal Standard: Germanium

% Recovery: 99

Lower Limit: 60 Upper Limit: 125

Concentration ug/L (ppb)

Chromium 284
Nickel 260
Copper 303
Zinc 28.3

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Date Received: Not Applicable 09/08/09 Date Extracted: 09/09/09 Date Analyzed: Matrix: Water Units: ug/L (ppb)

Internal Standard:

Copper

Zinc

Alaskan Copper Works Client: PO M04575, F&BI 909039 Project: Lab ID: I9-364 mb I9-364 mb.011 Data File: Instrument: ICPMS1 Operator: btb

Upper

Limit:

125

Lower

Limit:

60

% Recovery: Germanium 99 Concentration Analyte: ug/L (ppb) Chromium <1 Nickel <1

<1

<1

ENVIRONMENTAL CHEMISTS

Date of Report: 09/14/09 Date Received: 09/03/09

Project: Metro Self Monitor, PO M04575, F&BI 909039

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 909073-01 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria
Chromium	ug/L (ppb)	<1	<1	nm	0-20
Nickel	ug/L (ppb)	<1	<1	nm	0-20
Copper	ug/L (ppb)	14.2	14.1		0-20
Zinc	ug/L (ppb)	24.2	23.7	2	0-20

Laboratory Code: 909073-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Acceptance Criteria
Chromium	ug/L (ppb)	20	<1	99	50-150
Nickel	ug/L (ppb)	20	<1	104	50-150
Copper	ug/L (ppb)	20	14.2	100 b	50-150
Zinc	ug/L (ppb)	50	24.2	97 b	50-150

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	Percent Recovery LCS	Acceptance Criteria
Chromium	ug/L (ppb)	20	103	70-130
Nickel	ug/L (ppb)	20	107	70-130
Copper	ug/L (ppb)	20	105	70-130
Zinc	ug/L (ppb)	50	103	70-130

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- $\,$ nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

September 14, 2009



INVOICE # 09ACU0914-1

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M04575, F&BI 909039 - Results of testing requested by Gerry Thompson for material submitted on September 3, 2009.

federal tax id #(b) (6)

Sand Power To CAS	1 July	. 055	8	SAMPLE	RS (signature)			_	=			-				Page		of
Send Report To Seriel THOMPSIN Company ALASKAN Comper Ways Address 628 S Howard ST				PROJECT NAMENO. METTO SELF MONITOR					n	PO# MO4575				TURNAROUND TIME Standard (2 Weeks) USH Rush charges authorized by:				
City, State, ZIP Seate Phone # 206-571-6	e us	2813		REMARK	S				11	a K				H	□ Reti	0090 8 1711 58	MPLE DIS ther 30 day mples with testru	3 . N K
						T				ANA	LYS	ES	REQ	UES:	ΓED			
Sample ID	Lab ID	Date	Time	Sample 7	# of containe	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	Or Ca Mes						Notes
m04575	01	9/3/09	12:30	Hz	0 1							X				Г		10 N
**************************************			56 AF 988	i a		1	2.02					×		Γ	Γ			× '* ,
			2	- 8				1	\exists		7	-						
44 ¹ 78		, ,	7	4.4				7	7	7				3		1		***
											1							
										- 1						1134	10	
* 1				V.	N.	П										- 2		47 C
·			8.	44 (4)				7	7		1							-
TIWI :			1					7	7	7	1						· · · · ·	
iedman & Bruya, Inc.	SIGNATURE		PRINT NAME			IAME COMPA				NY	YY DATE			TIME				
12 16th Avenue West	Relinquistry	7	> Great Thomps						ACW				٠	9	13/09	1:15PA		
attle, WA 98119-2029 a. (206) 285-8282	Received by: Relinquished by:	law	A) (1)	Than	Phan Feb					<u>r</u>				V				
ax (206) 283-5044	Received by:											-						

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

September 14, 2009

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on September 3, 2009 from the Metro Self Monitor, PO M04575, F&BI 909039 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0914R.DOC